

Lot No.	Title	Description	Image
101	3/4" 1966 Davenport Model B 5-S	3/4" 1966 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 5423, Pick Off, Spindle Stopping, Enclosure	101-1.JPG 101-2.JPG 101-3.JPG 101-4.JPG 101-5.JPG
102	3/4" 1973 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7785	3/4" 1973 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7785, Threading, Pick Off	102-1.JPG 102-2.JPG 102-3.JPG 102-4.JPG 102-5.JPG
103	3/4" 1977 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 9422	3/4" 1977 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 9422, Pick Off, Spindle Stopping, Cross Drilling, Enclosure	103-1.JPG 103-2.JPG 103-3.JPG 103-4.JPG 103-5.JPG 103-6.JPG 103-7.JPG
107	3/4" 1971 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7252	3/4" 1971 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7252, Threading, Pick Off	107-1.JPG 107-2.JPG 107-3.JPG 107-4.JPG 107-5.JPG
108	3/4" 1951 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 2597	3/4" 1951 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 2597, Threading, Pick Off	108-1.JPG 108-2.JPG 108-3.JPG 108-4.JPG 108-5.JPG
109	3/4" 1968 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 5973	3/4" 1968 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 5973, Threading, Pick Off, Spindle Stopping	109-1.JPG 109-2.JPG 109-3.JPG 109-4.JPG 109-5.JPG
118	3/4" 1950 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 2564	3/4" 1950 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 2564, Threading, Pick Off, 4th Position Slide	118-1.JPG 118-2.JPG 118-3.JPG 118-4.JPG 118-5.JPG
119	3/4" 1971 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7251	3/4" 1971 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7251, Threading, Outrigger Transfer Back Saw Attachment	119-1.JPG 119-2.JPG 119-3.JPG 119-4.JPG 119-5.JPG 119-6.JPG
120	3/4" 1960 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 4120	3/4" 1960 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 4120, Threading, Pick Off, 4th Position Thread Rolling, Spindle Stopping	120-2.JPG 120-2.JPG 120-3.JPG 120-4.JPG 120-5.JPG

122	3/4" 1957 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 3327	3/4" 1957 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 3327, Threading, Pick Off, Spindle Stopping, 4th Position Slide with Milling	122-2.JPG 122-2.JPG 122-3.JPG 122-4.JPG 122-5.JPG
124	3/4" 1955 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 2993	3/4" 1955 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 2993, Threading, Pick Off, Spindle Stopping, 4th Position Slide	124-2.JPG 124-2.JPG 124-3.JPG 124-4.JPG 124-5.JPG
128	3/4" 1973 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7931	3/4" 1973 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 7931, Threading, Pick Off, Spindle Stopping, Enclosure	128-2.JPG 128-2.JPG 128-3.JPG 128-4.JPG 128-5.JPG
129	3/4" 1968 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 6076	3/4" 1968 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 6076, Pick Off, Spindle stopping, Enclosure	129-2.JPG 129-2.JPG 129-3.JPG 129-4.JPG
130	3/4" 1974 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 8217	3/4" 1974 Davenport Model B 5-Spindle Automatic Bar Machine, S/N 8217, Pick Off, Spindle Stopping, Cross Tapping Attachment, Enclosure	130-2.JPG 130-2.JPG 130-3.JPG 130-4.JPG 130-5.JPG 130-6.JPG